

Annex C

Site Photograph Log

SITE PHOTOGRAPHS

The site photographs below were taken by staff of Environmental Resources Management Southern Africa (Pty) Ltd. Kasantha Moodley and Janet Mkhabela undertook a site visit on 28 November 2013. Photographs were taken in the eight compass directions while additional photographs of relevant features on the site have also been included.

Photo 1 Existing Site Access (Off Tillet Road)



Photo 2 Facing North on the Proposed Site



Photo 3 Facing North-East on the Proposed Site



Photo 4 Facing East on the Proposed Site



Photo 5 Facing South-East on the Proposed Site



Photo 6 Facing South on the Proposed Site



Photo 7 Facing South-West on the Proposed Site



Photo 8 Facing West on the Proposed Site



Photo 9 Facing North-West on the Proposed Site



Photo 10 Second Site Access (Off Tillet Road)



Photo 11 Farmhouse to be used as Administrative Offices



Photo 12 *Outbuilding to be used as Change Facilities*



Photo 13 *Southern Property Boundary*



Photo 14 Facing North from the Farmhouse

